



Falcon 10



- Home
- Propulsion
- APU
- Airframe
- Operations
- About Us
- Contact

1978 Falcon 10 Available for Sale

See below for more information on this aircraft along with color photographs.
 Also available are the pilots who have flown *this* aircraft for the past 12 years (resumes available online).



AIRCRAFT

1978 Falcon 10
 Serial No. 106
 Reg No. N20CF
 8712 Aircraft Total Time
 7595 Total Landings (Overhaul at 5575)
 CAMPS- Factory Maintenance Program
 New Brakes: February 2009

Pilot services are also being offered with this aircraft.
 Resumes are available online by [clicking here](#)

ENGINES

TFE 731-2-2C Digital Engine Computers (DEEC)
 Engines on MSP Gold- Grumman Thrust Reversers
 LE: 8631 TT, 7278 cycles (O/h 2C Mode @ 8132 hrs)
 RE: 8596 TT, 7247 cycles (O/h 2C Mode @ 8101 hs)

CURRENTLY PRICED AT 1.4 MILLION USD

[View full size images online at www.teci.com](http://www.teci.com) .

For additional information, please contact:

Doug Young
 Program Manager
 Office. 417.781.8324
 Fax. 417.781.0800
doug.young@teci.com

AVIONICS

- 406 ELT
- RVSM
- SANDEL 3400 TAWS Configuration A
- Dual UNS-1LW with WAAS Certification (coupled)
- Ryan TCAD, ATS 9900 BX
- Universal 640MFD / Honeywell Primus 400 Radar
- Storm Scope
- HF Radio 7184U-5
- 2 Collins 105 Autopilot
- 2 Collins HSI/RMI
- 2 Collins VHF 20 Communication
- 2 Collins VIR 30 Navigation
- 2 Collins DME 40
- 2 Collins ADF 60
- 2 Collins TDR 90 Transponder
- Collins Digital Radar Altimeter
- 2 Collins 109 Flight Director

EQUIPMENT

- Freon Air Conditioner
- Aft Baggage Mod
- RECOG Lights
- Paint - 03/2001
- Interior - 03/2001
- Paint- Rated 9 out of 10
- Interior- Rated 9 out of 10

MAINTENANCE

C, 2C, B, 3B, A, 2A, 4A Complete: April 2007
 A, 2A, 4A, 4A+ Completed: February 2009